
PLAN VIEW SHOWING JACK SHAFT DRIVE IN MACHINE BASE
MOTOR DRIVE
TRANSMISSION DRIVE
SKF SPHERICAL ROLLER BEARING PILLOW BLOCKS #SA-22516-A
(12) JACK-SHAFT DRIVE "V" BELTS C-SECTION
(5) TRANSMISSION DRIVE "V" BELTS C-SECTION
JACK-SHAFT B-3745
JACK-SHAFT SHEAVE
TRANSMISSION GARBOR DRIVE SHEAVE
(6) ARBOR DRIVE "V" BELTS C-SECTION
ARBOR DRIVE
TRANSMISSION SHEAVE GUIDED
TRANSMISSION SHEAVE
(5) TRANSMISSION DRIVE "V" BELTS C-SECTION
FLYWHEEL PINION SHAFT C-3346
TRANSMISSION SHEAVE SHAFT C-3348
TRANSMISSION SHAFT LOWER C-3344
TRANSMISSION SHAFT FRONT C-3342
#30 S.S. OIL PUMP
#10 HALLIBRO CLUTCH SINGLE REVOLUTION
CROSSBEAM CLAMP
BASE CASTING
DIAMOND CHAIN COUPLING #D-6018
ARBOR SHEAVE GUIDED D-1896
STRAIGHTENER ARBOR C-237
STRAIGHTENER ARBOR DIE B-3651 - 10 REQ'D.
FEED ROLL B-3310
STRAIGHTENER ROLL B-3310
(6) ARBOR DRIVE "V" BELTS C-SECTION
BRAKE SHEW-RING
BRAKE LINING C-3058-1
MACHINE SERIAL NUMBER STAMPED HERE
GUIDE BAR CAPACITY ROD C-3206
GUIDE BAR SHAFT
C.B. SHAFT COUPLING C-3203
WIRE CLAMP SLIDE
SLIDE BAR CAMS
TIE ROD CAGE C-3335
TIE ROD
EXTENSION CHANNEL
CHANNEL COUPLING B-1722
UPPER RELEASE SLIDE D-1440
LOWER RELEASE SLIDE C-3577-2
SPRING #C-63
SPRING #M
SPRING #C-34
SPRING #T-4
SPRING #T-5
SPRING #T-6
SPRING #T-7
SPRING #T-8
SPRING #T-9
SPRING #T-10
SPRING #T-11
SPRING #T-12
SPRING #T-13
SPRING #T-14
SPRING #T-15
SPRING #T-16
SPRING #T-17
SPRING #T-18
SPRING #T-19
SPRING #T-20
SPRING #T-21
SPRING #T-22
SPRING #T-23
SPRING